Measure Points

1. [Set up the LEICA Disto S910](#)

2. Tap in section "Points" to add and measure a new point

3. Choose the type of points you want to add in the dropdown list

4. Tap `Disto` and aim the laser of the Leica Disto S910 on the first target you want to measure

5. Tap `Measure`
   Note: Tablet will BEEP after successful measurement and jump to the next number automatically

6. Repeat the last 2 steps until all points are measured
   Note: If you can't reach all points from this the current location please [Relocate measuring tool](#)

7. If all points are measured, tap `Close`

8. Tap and tap `upload to server`
   Note: Upload to server will affect the current show

9. shows successful upload

RELATED TOPICS

- [Define origin on stage](#)
- [Relocate measuring tool](#)
- [Validate Points](#)