

Something went wrong?

In case of a failure or error Message, see follow suggestions.

Missing anchors

Check the light on the front panel.

blue : all ok

red : POE power is good, no data -check cables or switch

off : no Power, check if the switch has POE capability and enough power, check cables

Calibration Result is bad

check the anchor postions. Check if large equipment hides the anchor.(loudspeakers, lamps,...)

Thin Materials are not a problem. See [MOUNT](#)

Fehlerbehandlung Messen

Pucks nicht in der Liste → Systemeinstellungen Pucks, Akku, einschalten

Fehler bei Mesh Ranging



From:

<https://manual.zackrack.com/> - **zackrack**

Permanent link:

https://manual.zackrack.com/doku.php?id=manual:measure_smart_failure

Last update: **2022/11/09 13:04**

