

Validate Points

This function calculates the position of a target you are aiming at with your measuring tool.

1. [Set up the LEICA Disto S910](#)
2. Go to Show Editor and tap Validate in the Points Section
3. Tap Disto and aim the laser on the the target you want to validate
4. Tap Measure

Note: Tablet will BEEP after successful measurement and calculate the coordinates of the target automatically

5. Tap Done to finish this process

RELATED TOPICS

- [Define origin on stage](#)
- [Validate Points](#)
- [Measure Points](#)

From:
<http://manual.zactrack.com/> - **zactrack**

Permanent link:
http://manual.zactrack.com/doku.php?id=manual:validate_points

Last update: **2018/07/26 21:35**

